

Technical Bulletin

Volume 22, Issue 03, September 2015

IN THIS ISSUE:	
New VersaPour 3.0 Diffuser	2
ICD - 85-2406C Sonic UDM Field Fix	3
New Patent Page on Lancer Website	4

TECHNICAL BULLETIN DISTRIBUTION

The Lancer Engineering Department publishes the Technical Bulletin every other month.

To subscribe or unsubscribe from the Tech Bulletin, go to lancercorp.com. Click on the Contact link and scroll down to Technical Publications.

Lancer Installation and Service Manuals, Instruction Sheets, previous Technical Bulletins, and a complete index of Technical Bulletin articles are also available at lancercorp.com.

For general questions about the Tech Bulletin, email techpubs@lancercorp.com or call (210) 310-7230.

CONTACT INFO

Lancer Sales: (800) 729-1500

Lancer Customer Service: (800) 729-1500

Lancer Warranty: (800) 729-1550 Lancer USA: (210) 310-7000

Canada: (210) 310-7187 Latin America: (210) 310-7000

International Sales: (210) 310-7063

Europe: 32-2-755-2390

Australia/New Zealand: 61-8-8268-1388

Email: custserv@lancercorp.com

Lancer Website: www.lancercorp.com





New VersaPour 3.0 Diffuser

Technical Bulletin Reference No. 2203-001

Lancer introduced a new VersaPour 3.0 diffuser (05-1593/04). The new diffuser uses black colorant but will retain the same specifications and functionality as the previous release, (05-1593/02).

The change will help differentiate VersaPour 3.0 diffusers from LEV 3.0 diffusers (05-3261).

The new part will be used in all VersaPour assemblies listed below:

19-171110	19-73331
19-73310	19-73410
19-73311	19-74331
19-73321	19-73341
19-73321-PB	

VersaPour 3.0 Diffuser PN: 05-1593/04



LEV 3.0 Diffuser PN: 05-3261



ICD - 85-2406C Sonic UDM Field Fix

Technical Bulletin Reference No. 2203-002

It has come to our attention there are issues regarding recently installed Ice Cooled Sonic UDM Dispensers. If one of these units has a manufacture date of or after August 7, 2015, then they require a quick and simple field fix. During assembly, the CVM valves were reversed and wired incorrectly. When the customer dispenses a carbonated drink, non-carbonated water is dispensed. The same goes for if a customer dispenses a non-carbonated drink, carbonated water is dispensed. The following are a set of instructions on how to perform this simple field test and get the dispenser functioning correctly.

Instructions

1. Remove Top Cover behind MVU tower.



(Incorrect Orientation)


2. When looking at the orientation of the valves from the front of the dispenser, the soda (black) CVM valve should be on the left side and the plain water (white) CVM valve should be on the right. From the top of the dispensing tower, reverse the black soda valve label with the white plain water label from the top of the CVM's.



With top cover removed

(Correct Orientation)

- 3. Open the back of the MVU tower from behind the splash plate.
- 4. Locate the wire harness connections for both the black soda valve and the white plain water valve.




(Locate Wires Labeled SODA and WATER)

- 5. Unplug the wires and swap the connections.
- 6. After swapping the wire harness connections, swap the black soda label and the white water label on the wire harnesses.
- 7. Repeat steps 1-5 for all CMV valves.
- 8. Replace back of MVU tower and replace top cover.

New Patent Page on Lancer Website

Technical Bulletin Reference No. 2203-003

Due to new Patent law, Section 287(a) of Title 35 of the United States Code, Lancer is no longer required to post a units patent information dirently onto the unit. Instead a new Patent Page was created on our website: *lancercorp.com/pantents*.



This new web page houses all of our patent numbers in one simple and easily accessable location. Each patent number is organized by unit and model number. A url reference of the patent page is located on all of our units name plate labels and dispenser mobile pages to coicide with the new patent law.

