

INSTRUCTION SHEET

NON-CARBONATED BRIDGE (NCB) SERVICE CODES

Primary	Secondary	Tertiary	Trouble Found	Corrective Action	Code					
Valve and Valve Accessories, LEV®	Non-Carb Primary Block	Body	Cracked	Replaced/Provided	*	W	SA	AA	E	C
			Leak	Replaced/Provided	*	W	SA	AA	T	C
		O-Ring	Cut/Torn	Replaced/Provided	*	W	SA	AV	G	C
			Leak	Replaced/Provided	*	W	SA	AV	T	C
			Missing	Replaced/Provided	*	W	SA	AV	W	C
		Cover	Cracked	Replaced/Provided	*	W	SA	GQ	E	C
			Missing	Replaced/Provided	*	W	SA	GQ	W	C
		Shutoff	Broken/Failed	Replaced/Provided	*	W	SA	MQ	B	C
			Leak	Replaced/Provided	*	W	SA	MQ	T	C
	Insert	Cracked	Replaced/Provided	*	W	SA	MR	E	C	
		Missing	Replaced/Provided	*	W	SA	MR	W	C	
	No Code Available	Not Applicable	Other	*	W	SA	Z4	9	N	
	Non-Carb Secondary Block	Body	Cracked	Replaced/Provided	*	W	SB	AA	E	C
			Leak	Replaced/Provided	*	W	SB	AA	T	C
			Missing	Replaced/Provided	*	W	SB	AA	W	C
		O-Ring	Cut/Torn	Replaced/Provided	*	W	SB	AV	G	C
			Leak	Replaced/Provided	*	W	SB	AV	T	C
			Missing	Replaced/Provided	*	W	SB	AV	W	C
		Shutoff	Broken/Failed	Replaced/Provided	*	W	SB	MQ	B	C
			Leak	Replaced/Provided	*	W	SB	MQ	T	C
		Insert	Cracked	Replaced/Provided	*	W	SB	MR	E	C
	Missing		Replaced/Provided	*	W	SB	MR	W	C	
	No Code Available	Not Applicable	Other	*	W	SB	Z4	9	N	
	Non-Carb Outer Connector Tube	O-Ring	Cut/Torn	Replaced/Provided	*	W	SC	AV	G	C
			Leak	Replaced/Provided	*	W	SC	AV	T	C
			Missing	Replaced/Provided	*	W	SC	AV	W	C
		Not Applicable	Cracked	Replaced/Provided	*	W	SC	XX	E	C
		No Code Available	Not Applicable	Other	*	W	SC	Z4	9	N
	Non-Carb Inner Connector Tube	O-Ring	Cut/Torn	Replaced/Provided	*	W	SD	AV	G	C
			Leak	Replaced/Provided	*	W	SD	AV	T	C
			Missing	Replaced/Provided	*	W	SD	AV	W	C
		Bushing	Cracked	Replaced/Provided	*	W	SD	GE	E	C
			Missing	Replaced/Provided	*	W	SD	GE	W	C
Not Applicable		Cracked	Replaced/Provided	*	W	SD	XX	E	C	
No Code Available		Not Applicable	Other	*	W	SD	Z4	9	N	
Not Applicable	No Code Available	Not Applicable	Not Applicable	Not Applicable	*	W	XX	Z4	9	N

Please refer to the Lancer web site (www.lancercorp.com) for information relating to Lancer Installation and Service Manuals, Instruction Sheets, Technical Bulletins, Service Bulletins, etc.

LANCER

6655 LANCER BLVD. • SAN ANTONIO, TEXAS 78219 USA • (210) 310-7000

FAX SALES

• NORTH AMERICA – 210-310-7245 • INTERNATIONAL SALES – 210-310-7242 • CUSTOMER SERVICE – 210-310-7242 •
• LATIN AMERICA – 210-310-7245 • EUROPE – 32-2-755-2399 • PACIFIC – 61-8-8268-1978 •

FAX ENGINEERING: • 210-310-7096

DATE: 06/07/96
P.N.: 28-0632/01