

### IN THIS ISSUE:

Updated Splash Plates to ICD Tower's.....	2
New Diffusers for LEV and VersaPour.....	3

### TECHNICAL BULLETIN DISTRIBUTION

The Lancer Engineering Department publishes the Technical Bulletin every other month.

To subscribe or unsubscribe from the Tech Bulletin, go to [lancercorp.com](http://lancercorp.com). Click on the Contact link and scroll down to Technical Publications.

Lancer Installation and Service Manuals, Instruction Sheets, previous Technical Bulletins, and a complete index of Technical Bulletin articles are also available at [lancercorp.com](http://lancercorp.com).

For general questions about the Tech Bulletin, email [techpubs@lancercorp.com](mailto:techpubs@lancercorp.com) or call (210) 310-7230.

### CONTACT INFO

**Lancer Sales:** (800) 729-1500

**Lancer Customer Service:** (800) 729-1500

**Lancer Warranty:** (800) 729-1550

**Lancer USA:** (210) 310-7000

**Canada:** (210) 310-7187

**Latin America:** (210) 310-7000

**International Sales:** (210) 310-7063

**Europe:** 32-2-755-2390

**Australia/New Zealand:** 61-8-8268-1388

**Email:** [custserv@lancercorp.com](mailto:custserv@lancercorp.com)

**Lancer Website:** [www.lancercorp.com](http://www.lancercorp.com)



# Updated Splash Plates to ICD Tower's

Technical Bulletin Reference No. 2204-001

It has been brought to our attention that there may be a small gap between the splash plate and tower for Lancer's 2300 series Ice Cooled Drop In units due to a miss-aligned drain tube. Lancer has corrected this issue by updating the splash plates to include a 1/4" extension of the side folds. These extensions cover the gaps on impacted units but will also become the standard splash plate in regular production. If you feel your unit was affected or would like to order the extended splash plate, please call Lancer Customer Service at (800) 729-1500.

**Coke CCP: 1069950**

**Old Splash Plate Part Number: 30-5424-01/01**

**New Splash Plate Part Number: 30-5424-01/02**



Small gap caused by mis-aligned drain tube



1/4" of side folds covers gap

# New Diffusers for LEV and VersaPour

Technical Bulletin Reference No. 2204-002

---

Lancer has made changes to the diffusers for both the LEV and VersaPour 3.0 valves. The LEV will have newly designed diffuser (PN: 05-3261) complete with a new feature meant to decrease the foam height of the finished drink. The new VersaPour diffuser will have a new black diffuser (PN: 05-1593/04) but will retain the same specifications and functionality as the previous release, (05-1593/02).

The change will help differentiate VersaPour 3.0 diffusers from LEV 3.0 diffusers.

**Previous 3.0 Diffuser  
PN: 05-1593/02**



**New LEV 3.0 Diffuser  
PN: 05-3261**



**New VersaPour 3.0 Diffuser  
PN: 05-1593/04**

