



LEV Fill Station Store Troubleshooting Guide

TROUBLE or SYMPTOM	POSSIBLE CAUSE	CORRECTIVE ACTION or REMEDY
Ŭ	NO POWER to FIII Station	A. Assure Fill Station in "AUTO" modeB. Check Power CordC. Check Circuit Breaker
Alarm Sound Does Not Stop	Pressure Switch is "ON"	A. Check CO2 and Syrup SupplyB. Check Syrup Bag Connection.C. Check Syrup Line Connection.
Weak Slush Brix	Valve Ratio Off	A. Reset Valve Ratio
High Slush Brix	Valve Ratio Off or Water Off	A. Reset Valve Ratio B. Restore Water Supply
Hopper Overfills	Probe Coating	A. Clean Sensor Probes

08MAY01 Copyright 2001 The Coca-Cola Co.

SAT-O-LFS-002